Quartz High-Pressure Sensor

Туре 6215...

for Ballistic Pressure Measurement to 6 000 bar

The front sealed high pressure sensor surtable for ballistic pressure measurement up to 6 000 bar.

- NATO Standard
- Extremely long service life
- Very good long term stability

Description

Compared to the shoulder sealing used so far, the front sealing technically improves the sensor considerably. The resulting main advantages are a considerably lower mechanical and thermal stress of the sensor, no mounting gap (small dead volume) and a largely reduced surface pressure in the sealing part.

The Type 6215... has been accepted by NATO as the successor to Kistler Type 6203 (AC/225 LG/3-SG/1). The existing NATO Standardization Agreements (STANAGs) and Manuals of Proof and Inspections (MOPIs) are being amended accordingly.

Application


Use for all ballistic measurements. Depending on the measuring configuration, the sensor can be installed with an additional thermal protection shield or a diaphragm protection.

Mounting

The front seal allows the use of an additional attachment.

Figure 3 shows the installation with thermal protection shield Type 6565A and thermal protective plate Type 1181A to reduce thermal shock error. For measurements in which the sensor is exposed to heat over the entire pressure profile (e.g. in pressure bombs and cartridge chambers).

Figure 4 shows the installation with diaphragm protector Type 6567. Recommended for measurements at the case mouth and along the measuring barrel as protection against mechanical damage from metal fragments and powder particles. It is essential to follow the operating instructions when machining the measuring hole and for installation.





Technical Data

bar	0 6 000
bar	0 600
bar	6 600
pC/bar	-1,4
kHz	>240
μs	1
%FSO	±1
bar/g	<0,002
bar/g	<0,005
g	25 000
g	10 000
%/°C	±0,02
°C	-50 200
pF	≈8
Ω	>1013
N∙m	20
g	12
	bar bar pC/bar kHz μs %FSO bar/g bar/g g g g %/°C °C pF Ω N·m

Page 1/2

©2007, Kistler Instrumente AG, Eulachstr. 22, 8408 Winterthur, Switzerland Tel +41 52 224 11 11, Fax +41 52 224 14 14, info@kistler.com, www.kistler.com

This information corresponds to the current state of knowledge. Kistler reserves the right to make technical changes. Liability for consequential damage resulting from the use of Kistler products is excluded.



Mounting Examples




Fig. 1: Dimensions of the measuring bore




Fig. 3: Installation with thermal protection shield Type 6565A and thermal protective plate Type 1181A

Accessories Included • Sealing ring 10x • Lubrication grease 1x	Type 1100 1063
Optional Accessories • Thermal protective plate • Thermal protection shield • Diaphragm protection • Sealing joint • Dummy plug • Adapter to pressure generator 6905A/6906 • Reduction sleeve • Cable special • Special drilling tool • Screw tap M10x1	Z14998 1699AA0,5 1327 1353
Surface finishing toolTorque wrenchTubular socket wrench hex. 8 mm	1300A25 1371B 1373




Fig. 2: Sealing part, sealing diameter




Fig. 4: Installation with thermal protector Type 6567

Ordering Key

		Type 6215 ∐
Quartz High-Pressure Sensor	-	
Quartz High-Pressure Sensor	A1	
with additional accessories included		
Types 1300A25, 1327, 1352, 1373		

Page 2/2

Г

This information corresponds to the current state of knowledge. Kistler reserves the right to make technical changes. Liability for consequential damage resulting from the use of Kistler products is excluded.

©2007, Kistler Instrumente AG, Eulachstr. 22, 8408 Winterthur, Switzerland Tel +41 52 224 11 11, Fax +41 52 224 14 14, info@kistler.com, www.kistler.com