

Mold Cavity Pressure Sensor

Unisens® with Front ø6 mm

Quartz sensor for cavity pressures up to 2 000 bar for injection molding of plastics.

- ideally suited for industrial applications
- sensor front can be machined to adapt to the cavity wall (except for coated versions of the sensor)
- exchangeable cable

Description

The sensor Type 6152AE consists of the Unisens quartz sensor for mold cavity pressure Type 6157BE with exchangeable cable, fitted in a rugged adapter. The sensor Type 6157BE with 4 mm front diameter comes flush with the adapter front with an annular gap of <10 µm and measures the pressure directly.

The pressure acts over the entire front of the sensor and is transmitted to the quartz measuring element, which produces a proportional electric charge (pC = Picocoloumb). This is converted into a voltage $0 \dots 10 \text{ V}$ in the amplifier and is then available as an amplifier output.

All parts of the sensor are corrosion-resistant. The exchangeable cable is screwed to the sensor with a tight seal. The connector is self-locking and splash-proof.

For multi cavity applications the sensor Types 6152AA... and 6152AC... are used without the single-wire connector Typ 1839. The Multi Cavity Set Type 6829A... and the Multi Sensor System Type 6831A... are described in the appropriate data sheets.


This sensor is available with several types of connecting cables (see page 2).

Application

This diaphragm-free sensor measures mold cavity pressures up to 2 000 bar during injection molding. It is particularly suitable for optimizing, monitoring and controlling the injection molding process of thermoplastics, elastomers, thermosets and SMC.

Type 6152A...

Patent No. US 6,212,963



For abrasive melts (e.g. filled with glass fibers or carbon fibers, thermosets, BMC/SMC), these sensors are available as Types 6152ACE/ADE with a coated front.

With low viscosity melts (e.g. thermosets, SMC/BMC, IC sheaths), the silicone-filled Types 6152AAAE/ACAE must be used.


Technical Data

Range	bar	0 2 000
Overload	bar	2 500
Uniform sensitivity	pC/bar	-9,4
Linearity, all ranges	% FSO	≤±1
Operating temperature range		
Mold (Sensor, Cable)		
6152AA/AE/AA/AC	CC	200
6152AB/AD	°C	300
Melt (at front of sensor)	°C	<450
Connector	°C	0 200*
Insulation resistance		
at 20 °C	ΤΩ	>100
at 300 °C	ΤΩ	>0,01

* During machine down time, the mold temperature may rise to 240 °C without damaging the sensor; however, this may lead to measuring errors.




Pressure Sensor Type 6152AA.../AC




Sensor with coaxial cable for temperature up to 200 °C.

Pressure Sensor Type 6152AB.../AD



Special version of the sensor Type 6152AE with extended operating temperature range up to 300 °C. This sensor is suitable for special materials. Exchangeable steel-braided polyamide cable (Kapton) with connector.

Pressure Sensor Type 6152A...E



Sensor using single-wire technique for easy installation. The sensor Type 6152AEE is provided with a single-wire cable with a very small cross-sectional area and can be installed flexibly in the injection mold. The single-wire cable is exchangeable and

can be cut to length as required. With the single-wire technique, electrical shielding is provided by the mold. It is therefore essential for the cable and connector to be completely integrated in the mold. To ensure easy installation, a connector is included which is self-locking and splash-proof.

The following sensors with single-wire technique are available:

Types 6152AAE, 6152AAAE, 6152ACE and 6152ACAE

Special versions

Coated front (abrasion protection)

Type 6152AAE with coated front: Type 6152ACE
 Type 6152ABE with coated front: Type 6152ADE

Silicone-filled gap

(not possible with Types 6152ABE and 6152ADE)

- Type 6152AAE gap filled with silicone: Type 6152AAAE
- Type 6152ACE gap filled with silicone: Type 6152ACAE

Montage


The sensor is normally fixed in the mounting bore with the mounting nut (Type 6453), but a spacer sleeve (Type 6459) can also be used.


The sensor front forms part of the cavity wall. The sensor must therefore be adapted so that its front comes exactly flush and leaves no impression on the molded part. The front can be further machined up to 0,5 mm (except with a coated front!). Full details may be found in the operating instructions.


The sensor is center aligned in the 6 H7 bore.



Cable and Amplifier for Measuring Chain with Sensor Type 6152A...









Cable Type 1667B (BNC Connector)	Cable Type 1672B (TNC Connector)
Type 5039Axx2	Type 5039Axx1
Type 5049Axx2	Type 5049Axx1
Type 5155Axx2x/Axx4x/Axx8x	Type 5155Axx1x/Axx3x/Axx7x
Type 5063A1 in Type 2859A/2865A	

Fig. 1: Sensor Type 6152A... with Charge Amplifier Typ 5155A... or Signal Conditioner Type 2859/2865A...





4-Channel Cable Type 1995A to Connector Type 1708A	8-Channel Cable Type 1997A on Connector Type 1710A
Type 2869A0xx	Type 2869A2xx
Type 2869A1xx	

Fig. 2: Sensor Type 6152A... with Monitoring System CoMo® Injection Typ 2869A...



Installation Examples




Fig. 3: Installation with mounting nut Type 6453




Fig. 4: Installation with spacer sleeve Type 6462




Fig. 5: Mounting plate (Art. No. 3.520.328)




Fig. 6: Sensor with machined front (Types 6152AA... and 6152AB... only)




Fig. 7: Sensor, cable, mounting plate (Art. No. 3.520.328) and identification label (Art. No. 3.520.899)




Fig. 8: Connector (Type 1839)




Accessories Included Mounting nut	Art. No./Type 6453	 High temperature extension cable Viton Fischer SE102A014 – TNC pos., 	
Mounting plate	3.520.328	Length 2 m	1672B2
(for sensor with cable only)		Length 5 m	1672B5
identification label	3.520.899	Spacer sleeve	6462
 Connector (for single-wire technique only) 	1839	 4 channel connector for 	1708A
• Single-wire cable, with the length of 1,5 m		Type 6152AG and G1	
(ready installed with sensor, for		8 channel connector for	1710A
single-wire technique only)	1666A1	Type 6152AG and G1	
• Single-wire cable, with the length of 5 m		Dummy sensor	6552
(ready installed with sensor, for		• O-ring, ø2,5x0,65 mm,	
single-wire technique only)	1666A3	(for Type 6152AAE only)	1100A57
		• O-ring, ø2,5x0,65 mm,	
Optional Accessories	Art. No./Type	(for Type 6152ABE only)	1100A67
High temperature extension cable Viton®		()	
Fischer SE102A014 – BNC pos.,		Mounting Accessories	Туре
Length 2 m	1667B2	Socket wrench	1383
Length 5 m	1667B5	Extraction tool	1315A
8 8 9		Key for mounting nut	1352
		• Tap M 12x1	1355
		Mounting piece for connector	1401

Ordering Key

Sensor	
up to 200 °C	Α
up to 300 °C	В
up to 200 °C, sensor front coated	С
up to 300 °C, sensor front coated	D
Gap between sensor adapter filled with Silicone	Α
(only for Types 6152AA and 6152AC)	
C.1.1	
Cable Coaxial cable, L in m	0,2
Coaxial cable, L in m	0,2 0,4
Coaxial cable, L in m (Type 6152AB and Type 6152AD only available as	
Coaxial cable, L in m (Type 6152AB and Type 6152AD only available as	0,4
	0,4 0,6
Coaxial cable, L in m (Type 6152AB and Type 6152AD only available as 0,4 and sp) Coaxial cable with special lengths, specify L in m	0,4 0,6 0,8

G

G1



Type 6152AAE or 6152ACE (L = 1,5 m)

Type 6152AAE1 or 6152ACE1 (L = 5 m)

from the use of Kistler products is excluded.

without connector

without connector



Type 6152A 🔲 📮 🛚

Page 5/5